



THE RIGHT PEOPLE. THE RIGHT BUS.

Valid from
May 1st to June 30th, 2012



1 888 416-9333

Prices subject to change
without notice.

Dynamic Specialty Vehicles Ltd.
18550 96th Avenue Surrey, B.C.
CANADA V4N 3P9
Phone: 604-882-9333
Fax: 604-882-3555


Roof Hatch

199.74

SPECIALTY
MANUFACTURING CO.



Calipers



Bosch	
R55850 (rebuilt)	69.74
55850 (new)	99.47
Bendix	
R55250 (rebuilt)	59.74
55250 (new)	94.47
Meritor	
4 pistons 2 holes (new)	239.74
4 pistons 3 holes (new)	249.47

Hardware Kits

for Bosch calipers

Partial	23.47
Complete	52.74



for Bendix calipers

Without spacer	9.74
With spacer	19.47



Meritor	5.74
----------------------	------



Nitrile Gloves

12.74



Large

Drag Links



VISION

2004 to 2009	129.47
2010 and above	124.74

CV200

1993 and above (8 000 lb, 9 000 lbs)	79.47
1997 and above (11 000 lbs)	89.74

International

1990 to 2004 (8 000 lbs)	92.47
1990 to 2004 (10 000 lbs)	69.74
2005 and above (10 000 lbs)	124.74


FREIGHTLINER

FS-65 (10 000 lbs)	149.47
C2	149.74

MINIBUS

E-350, 450 1992 to 2007	54.47
Savana 1996 to 2002	94.74

Wheel Oil Seals



370 series

370008A	34.74
370150A	19.47
370199A	29.74
370211A	32.47

380 series

380001A	25.47
380003A	35.74
380023A	32.47
380025A	26.74

Crankcase Ventilation Kits



Cummins

ISB	59.74
ISC	79.47





www.dynamicspecialty.com

Prices subject to change without notice.

Tie rod ends



Vision

2004 to 2006	8 1/8"69.74
2007 and above	10 1/4"62.47

GM

CV-200	1993 and above (9 000, 11 000 lbs)62.74
--------	------------------------------------	-------	---------------

International

PC-3000	1992/97 (10 000 lbs)34.47
PC-3000	1998/2004 (10 000 lbs)29.74

TC-2000, TC-3000

1992 to 2002			
132" to 160" WB	(12 000 lbs)29.74
174" to 263" WB	(12 000 lbs)34.47
2003 to 2007	29.74

Freightliner

FS65	(10 000 lbs)29.74
------	--------------	-------	---------------

Minibus

E-350/450	1992 to 2007		
Left outer	19.47
Right outer	19.74
Left inner	49.47
Savana	1996 to 2002		
Inner	19.47
Outer	24.47
Savana	2003 and above		
Inner	92.74
Outer	34.47

4" Seal Clamps, ID, OD



TorcTite®
6.47



Walker
8.74

First Aid Kits



Canada CSA-D250 **.69.74**

Vinyl Repair Compound

16 oz.19.74
32 oz.36.47
128 oz.139.74



Water Pumps (New)



Cummins ISB79.47
International DT466E S/N : S2000000 and below49.74
International DT466E S/N : S2000000 and above99.74
International T444E194.47

Weatherstrip Self-Adhesive Neoprene



		FT
1/8" X 1/2" X 50'015
1/8" X 3/4" X 50'019
3/8" X 3/4" X 25'034
1/2" X 3/4" X 15'039

Wiper Blades (summer) "exact Fit"



17-17.47	22-18.47
18-17.74	22-48.74
18-26.74	24-111.47
20-17.74	28-916.74

Turn Signal Switch

Replace International 3566936C91

76.47

